

Technical Newsletter

#tnl2022-0014e
1 / 1



DAD3350 Maintenance Manual Request for Correction in the Part Number of the Blade Conditioning Chip

Purpose of this Technical Newsletter

We have found that the part number of the blade conditioning chip for hub mount described in the Maintenance Manual for model DAD3350 remains unchanged. Please check the details and correct them.

Applicable Maintenance Manual

The object part number is described in Section 2 [Flange/Hub Mount Conditioning] of Chapter C in the Maintenance Manual below.

Applicable model	Part No. of the Maintenance Manual	
DAD3350 equipped with old-type electrical component (Production ID: KB1*** – KB4***)	Japanese	UKBSMJH014D
	English	UKBSMEH014D

Correction details

The old part number below cannot be purchased due to discontinuation. Please place an order with the new part number.

Item	Part No. [old]	Part No. [new]
Conditioning chip (for hub mount)	BVDR0067	LKKN-010049-0

Inquiries

Please contact your local DISCO sales representative or customer engineer if you have any questions regarding this matter.
