

Technical Newsletter

#tn12023-0001e
1 / 1



Change to Film Material inside Upper Lid of 20 L Container for HogoMax102/103


Notification

Due to the ceased production of the film inside the upper lid of the 20 L container for HogoMax103-10/-15 and HogoMax102-10, a substitute film will be used.
Based on evaluation conducted at DISCO, it was confirmed that there were no differences in liquid quality after this change.
Thank you for your understanding and cooperation.

Applicable Products

Model number	Volume (L)	Dilution rate	Part no.
HogoMax103-10-20L	20	1.0	KS13-102021-0
HogoMax103-15-20L		1.5	KS13-152021-0
HogoMax102-10-20L		1.0	KS14-102021-0

Changes

Items	Before change	After change
Materials	Fluorine material	Polyethylene material
Location used	 <p>Film* *Surface of foam packing is coated with film.</p>	

Switchover Timing

Change will be implemented from products manufactured in July 2023.

Notifications

- 1) This change is equivalent to a change in the contents of the delivery specification sheet. However, for simplification purposes, this notification is being issued in place of another delivery specification.
- 2) No part number change will accompany this change.

Inquiries

For inquiries regarding this matter, please contact a DISCO sales representative or customer engineer.